

Product/maintenance information No. 2015-2

Date: 2015-12-15
Implementing date: 2015-07-01
Approved by: Martin Johansson

Temperature alarm

Background

Broken shaft seals on the Grundfos pumps is a common problem and there can be many reasons for it. High inlet temperature or running against closed valve etc. It is a "tear-and-wear" part so it should be changed from time to time depending on operating conditions and hours. But especially on pumps with frequency converters, the problem can be very costly if not changed in time.

Please, see picture on page 2.

Action:

From July 2015, all pumps with frequency converters has a temperature switch for stopping the unit if (for some reason) the temperature gets over 80 degrees Celsius. It will not affect the price and it will be delivered as standard. Article number is clearly stated in the manual.

If you have any questions, please contact us.

Lagafors Fabriks AB



Product Manager
Martin Johansson

Picture

